
FIGURE 1



90

200

in-line front-of-line portion 300A

V/C 302 V/C 302

		T		
D/A	cure	plasma	W/B	plasma
304	306	308	310	312
307	30			

In-line end-of-line portion 300B

V/C	V/C	V/C
302	302	302
		•

mold	PMC	SBA	saw	sort
314	316	318	320	322

in-line finish portion 300C

V/C 302	V/C 302	V/C 302	
mark	FVI	T/R	_
224	326	328	




Figure 4

.....

daure 5





FIGURE 6






FIGURE 8




FIGURE 9




FIGURE 10




FIGURE 11




FIGURE 12

